

Scott D. Kelloway, P.E.

Professional Civil and Environmental Designs and Inspections.
148 North St. Andover, Ma. 01810 Phone: (978) 682-5054
Ma. Lisc #40122

3/14/2005

Andover Conservation Commission
Town Office Building
36 Bartlett St.
Andover, Ma. 01810-3882

Dear, Conservation Commission.

Please refer to the attached field inspection reports of site monitoring for the property located at 19 Basswood Lane, described on town map #156, lot #65. DEP File #090-0866.

The construction activities on this site, for this month are as follows:

- Continued construction of single family home.

Site is mostly snow covered, there has been no earth work on this site this month. Siltation barrier is currently in suitable condition. There has been no disturbance to restricted areas. All site grading is consistent with approved site plan. There has been no erosion to wetland areas.

At this time all work on this site is being performed in compliance with the conditions stipulated in the Order of Conditions.

If you have any questions or concerns, please feel free to contact me at address and phone number listed above.

Sincerely,

Scott D. Kelloway
Scott D. Kelloway, P.E.



CC. Todd Waken, Fieldstone Meadows Dev. Corp.

Scott D. Kelloway, P.E.

Professional Civil and Environmental Designs and Inspections.

148 North St. Andover, Ma. 01810

Phone: Office(978) 682-5054, Nextel(978)479-5648

Ma. Lisc #40122

Field Inspection Report

Location: ANDOVER, 19 BASSWOOD DR. Date: 3/11/05

Lot(s)#: _____ Type of Report: WEEKLY Storm Event: No 242

Weather: LT. SNOW 32° DEP File #: _____

(Order of Cond) Registry: _____

Book: _____ Page: _____

Description of Site Work:

* CONT. CONSIST OF SINGLE FAMILY HOME.
* NO EXTRA EXCAVATION, JUST SNOW REMOVAL ELSEWHERE ON SITE.

Inspection Report (cont. on back if necessary):

- NO ENCROACHMENT TO M.P.?
- SITUATION EXAMINED IN SURFACE COND.
- EXPOSED EARTH STABLE?
- CATRA SACK IN ROADWAY HAS BEEN EMPTIED.

Recommendations: NONE

Signature: [Signature] Date: 3/11/05

Scott D. Kelloway, P.E.
Professional Civil and Environmental Designs and Inspections.
148 North St. Andover, Ma. 01810
Phone: Office(978) 682-5054, Nextel(978)479-5648
Ma. Lisc #40122

Field Inspection Report

Location: ANDOVER 19 BASWOOD DR. Date: 3/4/05

Lot(s)#: _____ Type of Report: WEEKLY Storm Event: NO RAIN

Weather: SUNNY 30 DEP File #: _____

(Order of Cond) Registry: _____

Book: _____ Page: _____

Description of Site Work:


SAME AS LAST WEEKLY REPORT

Inspection Report (cont. on back if necessary):

- ELEVATION BARRIER SUITABLE
- NO ENCROACHMENT W/IN M.P.Z.
- SITE STABLE NO EVIDENCE TO WETLAND USE AREAS
- COMPLIANT w/ ALL OF COND.

Recommendations: NONE

Signature

 Date: 3/4/05

Scott D. Kelloway, P.E.

Professional Civil and Environmental Designs and Inspections.

148 North St. Andover, Ma. 01810

Phone: Office(978) 682-5054, Nextel(978)479-5648

Ma. Lisc #40122

Field Inspection Report

Location: ANDOVER, 19 BASSWOOD DR Date: 2/25/05

Lot(s)#: _____ Type of Report: Weekly Storm Event: _____

Weather: CLEAR/SUNNY 25° DEP File #: _____

(Order of Cond) Registry: _____

Book: _____ Page: _____

Description of Site Work: _____
o CONT CONST SINGLE FAMILY HOME.
* NOTE NO WORK INVOLVING THE UN-ATTACHED GARAGE YET.
- SITE NOW COVERED MOSTLY, DRIVAS CLEARED FOR ACCESS.

Inspection Report (cont. on back if necessary): _____
- SITUATION BACK IN SUITABLE CONDITIONS
- NO ENCROACHMENT w/in N.P. 2
- EROSION TO WETLANDS AREAS
- CATCH SACKS IN C.B. NEED TO BE EMPTIED

Recommendations: NOTIFIED CONTRACTOR TO HAVE CATCH SACKS
W C.B. EMPTIED.

Signature: [Signature] Date: 2/27/05

Scott D. Kelloway, P.E.
Professional Civil and Environmental Designs and Inspections.
148 North St. Andover, Ma. 01810
Phone: Office(978) 682-5054, Nextel(978)479-5648
Ma. Lisc #40122

Field Inspection Report

Location: ANDOVER 19 BASSWOOD Date: 2/18/05

Lot(s)#: _____ Type of Report: WEEKLY Storm Event: NO ZTR

Weather: CLOUDY 29° DEP File #: _____

(Order of Cond) Registry: _____

Book: _____ Page: _____

Description of Site Work:

- CONT CONST OF SINGLE FAMILY HOME
- NO SIGNIFICANT SITE WORK

Inspection Report (cont. on back if necessary):

- SLOTTED BANKER IN SUITABLE CONDITION
- NO EROSION TO WEIR AND RESOLVE AREA
- NO ENCROACHMENT W/IN N.P.Z.
- COMPLIANT W/ ORDS OF COND.

Recommendations: NONE

Signature: _____

Date: 2/18/05